



Receipt Stop Instructions

5500 MWS and 5500 SMP

Use the below instructions to turn the Receipts Stop function on or off for 5500 model registers – MWS and SMP.

1. Press MGR #
2. Enter manager number
3. Press MGR #
4. Press SHIFT KEY
5. Press KIDS SIG
 - a. If RS shows at bottom of screen receipts will NOT print after each order
 - b. If RS is not shown at bottom of screen receipts WILL print after each order
6. Once you have the setting you want, press SHIFT KEY again
7. Press MGR #
8. Enter 0
9. Press MGR #